

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Reason For Inspection:

Predicted Precipitation Source:

1st Weekly

2nd Weekly

10.27.11 State Route (SR) / US Route or Road Name and Description: Are corrective actions required by this inspection report (Y/N): No Wolf River Blvd. County(ies) TDOT PIN: NPDES Permit (NOC) #: Number of Un-Corrected Number of Recurring Number of New Number of New Corrective Actions: Corrective Actions: Sediment Releases: Sediment Releases: Shelby 101615 TNR153299 TDOT Construction No. TDOT Contract No.: Contractor: 0 0 7994-1535-54 Acuff Enterprises Inc. I certify, under penalty of law that this document and all attachments were COG EPSC Inspector and Title (print or type): Signature: prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated Gerald "Jerry" Stanfill information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the Contractor EPSC Inspector and Title (print or type): information, I cerify that inspections of storm water discharge points (outfalls), and of erosion and sediment controls have been performed as recorded in the table Tom Acuff above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as COG EPSC Project Manager Signalure recorded in the table above. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment for (print or type): knowing violations Timothy Bierdz TDOT EPSC Inspection Weekly Rainfall Data Log TDOT/Contractor Agrees with Inspection Report: Predicted Rainfall Rainfall Rainfall Rainfall Rainfall Rainfall NO Date Day of Week Precipilation Gauge 1 Gauge 2 Gauge 3 Gauge 4 Gauge 5 Gauge 6 Duration If No, explain and initial: (%) (in) (in) (in) (in) (in) (in) (hr) Sunday N/A N/A N/A N/A 10 Monday 0 N/A N/A N/A 10.2411 0 N/A 0 10-25-11 Tuesday N/A N/A N/A N/A N/A 10.26.11 Wednesday 10 N/A N/A N/A 10-27-11 Thursday 50 0 0 N/A N/A N/A N/A 10.28.11 Friday 30 N/A N/A N/A N/A 0 N/A 10.29.11 Salurday N/A N/A N/A 0 10.30.11 Sunday N/A N/A N/A N/A N/A Monday N/A NIA N/A (Additional pages may be attached, if needed)

www.weather.com

Page 1 of 8

	i ici	HE	53%	
6	a	S.		<u>)</u>
	AGRIC	a.M	URE	I N
1/4		MER 796	1	/

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	10/27/2011
------	------------

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	10/27/2011		22,35	FM	Weekly cleaning will be required, until furthe notice.
1A	1	21+50	RT	10/27/2011		41	FM	Const. of RCBC Pedestrian Underpass in progress.
1B	1	22+00	RT	10/24/2011		41	FM	Backfilling RCBC in progress.
1C	1	21+00	LT	10/27/2011	T = 10-6-11	12,15,35,41	FM	Monitoring BMP's in place.
2A	1	33+50	LT,CL	10/27/2011		12,15,16,24	FM	Corrections have been made. See Photos
2B	1	35+50	LT	10/27/2011		16,24	FM	Weekly cleaning for stream crossing required, unti- further notice. See Photo
3	1	34+50	LT	10/27/2011		16	FM	Monitoring BMP in place. See Photo.
4	1	40+00	RT	10/27/2011	T = 10-24-11	15,16,43	FM	Temporary stabilized. Monitoring BMP's in place.
5A	1	49+00	RT	10/24/2011		16,33	FM	No Const. Activity during Inspection. Monitoring BMP's in place.
5B	1	50+00	RT	10/24/2011		9,16,33	FM	No Const. Activity during Inspection. Monitoring BMP's in place.

EROSION AND SEDIMENT CONTROL MEASURE CODES

		ION A	ND SEDIMENT CONTROL MEASURE	COD	ES		CONDITION CODES
1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	Ü	FARM OF REAL RESIDENCE OF THE STATE OF THE S
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner		Upgrade Needed (Failure Noted)
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	R FM	Replacement Needed Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	C	May be desir
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	·	Cleaning Needed
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	1	Increase Measures
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	W	Too Wet to Work Conditions
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37		RO	Repeat Occurrence
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing		Concrete Washout, other pollution Issues	SR	Sediment Release
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	38	Berm (soil, riprap, rock)	FS	Final Stabilized
12	Machined Rip Rap		**************************************	39	Gabion	S	Stable (No Action Needed)
13	NSO 07 (1993)	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
10000	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	
EDGO I-				43	Stream Realignment	(= 1,0	

State/US	Route	or Road	Name:
Julia le/UC	Noute	UI RUAU	Maille.

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54

700	54.	35	27.	-54

TDOT Contract No.:

Date	10/27/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
								Weekly cleaning for stream crossing
5C	1	44+00	LT	10/27/2011		16,24	FM	required. (BMP's incomplete @ New Channel Realignment. See Photo)
6	1	56+00	LT	10/24/2011			FM	Pond has been drained. Currently Stable.
7	1	60+00	RT	10/24/2011		16, 33	FM	Currently Stable, Monitoring BMP's.
8A	1	73+00	RT	10/27/2011		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	S	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	10/27/2011		16,35,42	FM	Active construction zone. Monitoring BMP's. See Photo
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	FM	Monitoring BMP's. Weekly watering required until seed establishes.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	FM	Weekly watering required until seed establishes.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	FM	Weekly watering required until seed establishes.

EROSION AND SEDIMENT CONTROL MEASURE CODES

CONDITION CODES Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 30 Temporary Mulch Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 **Brush Barrier** 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing Cleaning Needed 6 Sediment Removal 20 Enhanced Silt Fence Riprap Outlet Structure 34 Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection RO 36 Sediment Dam Repeat Occurrence Sediment Trap / Basin 37 9 23 Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 38 10 24 Temporary Stream Crossing Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Other (O31): Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling Other (O#2):____ 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#3): 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction**

State/US	Dougle or	Dood	Mama
State US	Noute of	rvuau	maille.

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date 10/27/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM	Weekly watering required until seed establishes.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM	Currently active construction site. Sand bag upstream, remove daily during construction.
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM	No work done in this area on inspection date.
10C	2	85+50	LT	9/29/2011		15,16,35,41	FM	No work done in this area on inspection date.
10D	2	84+50	LT	9/29/2011		10,15,16,35,41	FM	No work done in this area on inspection date.
11A	2	92+50	RT	10/24/2011		35,41	FM	Backfilling RCBC in progress.
11B	2	92+50	LT	10/6/2011		10,32,35,41	W	Remove floatables. See photo
11C	2	92+00	LT	10/6/2011		10,32,35,41	W	Remove floatables. See photo
	1	11+28	LT	10/27/2011		19,35	FM	Daily cleaning is required, until further notice
	1	13+40	RT	10/27/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75 EROSIO	CL N AND SEDIME	10/27/2011	MEASURE CODES	23,29,30	FM	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily 29 M Maintenance 2 Haul Roads Dampened for Dust Control U Temporary Diversion Berm or Ditch Temporary Mulch 30 Upgrade Needed (Failure Noted) 16 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Catch Basin / Storm Inlet Protection С 5 **Brush Barrier** 19 33 Temporary Silt Fence with Backing Cleaning Needed Sediment Removal Enhanced Silt Fence Increase Measures 6 20 Riprap Outlet Structure 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 39 Gabion S Stable (No Action Needed) 11 25 Turbidity Barrier / Silt Boom 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod Other (O#3): 28 Mineral Aggregate Base on Subgrade Bridge Construction

State/US	S Route	or	Ro

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:
		: 11 () () () () () () () () ()		

Date	10/27/2011	

Outfall Name or Station No. *(Existing Structure)	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
* 109+51	2	East side of WRB	RT	10/27/2011		19,22	FM	Daily cleaning will be required, until further notice.
* 109+11	2	South side of Farmington	RT	10/27/2011		19,22	FM	Daily cleaning will be required, until further notice.
* 12+80	1	North side of WRB	LT	10/27/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	Walking Trail 36+00	LT	7/20/2011	T = 7-20-11	5,35	S	Currently stable, Monitoring BMP's
	11	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	S	Currently stable.
		Sta. 13+40 - Sta. 107+75	LT, RT or CL	10/13/2011		30	FM	Haul roads dampened frequently for dust control, until further notice.
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
	1	6+75	LT	10/27/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	S	Currently stable, Monitoring BMP's
	1	34+00 FROSI	RT ON AND SEDIMEN	8/25/2011	T= 8-25-11	16	S	Currently stable, Monitoring BMP's CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

						2.2	
1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

EPSC Inspection

Page 5 of 8

OF THE STATE	
A SA	
AGRICULTURE	
OFFICE OF THE PROPERTY OF THE	

0 td Name:	Wolf River Blvd.	TDOT Construction No.;	79954-3537-54	TDOT Contract No.:


Date _____ 10/27/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed establishes.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed establishes.
	1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	FM	Currently stable, monitoring BMP's.
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	FM	Currently stable, monitoring BMP's. Weekly watering required until seed establishes.
* 108+37		North side of WRB	LT	10/27/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	FM	Currently stable, monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES


Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure **Enhanced Silt Fence** Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing Berm (soil, riprap, rock) Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 S Stable (No Action Needed) Gabion 12 Machined Rip Rap 26 Temporary Stream Diversion Other (O31): Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Haul Road Other (O#2): 41 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):

CONDITION CODES






City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Outfall 8C Sta. 71+00 LT BMP's Added (FM)



City C

City of Germantown 1920 S. Germantown Road Germantown, TN 38138